

SABLE PERMIAN RESOURCES, LLC
Daily Completion Partner Report

Report Date 10/16/2017
AFE # 1550466
Total AFE 4,547,178

UNIVERSITY 11 RE 932HA
WELL NO. 156

API 42383398290000	State TEXAS	County REAGAN	Well Config HORIZONTAL	Ground Elevation (ft) 2,666.00	RKB (ft) 21.00	Well Status COMPLETION	Well Sub-Status COMPLETING	Completion Date
-----------------------	----------------	------------------	---------------------------	-----------------------------------	-------------------	---------------------------	-------------------------------	-----------------

Job Information					
Job Category COMPLETION	Primary Job Type COMPLETION - ORIGINAL	Secondary Job Type	Start Date 9/18/2017	End Date	
AFE Number 1550466	Supplemental AFE Number	Daily Field Est (Cost) 31,686	Cum Field Est (Cost) 2,313,115		
Number of Stages (ft) 46	Lateral Length (ft) 9,965	Time Since LTI (days)	Time Since Reportable Incident (days)		

Daily Contacts					
Contacts COMP SUPT, BEN MCCORMICK, ; COMP ENG, CORLEY WALTERS, ; COMP SUPT, DALE BLOCKER, ; CSV, JERRY GOSA, ; CSV, BO WELLS,					

Daily Operations					
Operations Summary 0 EHS; 24 hrs NPT; Waiting on CT Unit to arrive					
Planned Operations Frac Ops					

Time Log									
Start Time	End Time	Dur (hr)	Cum Dur (hr)	Activity	Inactive?	Comments	Unschd Type	NPT	
06:00	06:30	0.50	0.50	DOWNTIME	No	Install T-clamp on WL below bottom sheave, SI & lock down WL rams #2 & #3.		Yes	
06:30	07:00	0.50	1.00	DOWNTIME	No	Monitor pressure for 15 min, WL BOP's holding.		Yes	
07:00	08:30	1.50	2.50	DOWNTIME	No	Break off lubricator just below tool trap, pick up lubricator & install WL clamp above BOP's & strip WL down through the grease tubes, found a hi-strand that caused a birds nest in the wire not allowing it to pass through the grease tubes.		Yes	
08:30	09:30	1.00	3.50	DOWNTIME	No	Cut out the birds nest & clean up the hi-strand.		Yes	
09:30	12:30	3.00	6.50	DOWNTIME	No	SD due to severe weather moving into the area.		Yes	
12:30	13:15	0.75	7.25	DOWNTIME	No	Straighten out twisted top sheave, take off top WL clamp, re-install lubricator on the BOP's, equalize pressure above WL rams to well pressure (2,000 psi).		Yes	
13:15	13:45	0.50	7.75	DOWNTIME	No	Pull 55' of wire out of hole when tension climbed from 300lbs to 1,200lbs, pulled up to 1,500lbs of tension when the wire pulled thru the grease tubes, after pulling another 22' tension climbed to 1,800lbs, stopped pulling & slacked off, SI WL ram #3, bled off lubricator, monitor for 15 min, break off lubricator and inspect wire.		Yes	
13:45	14:30	0.75	8.50	DOWNTIME	No	Install top wire clamp just above BOP's, wire came free while attempting to pick up the lubricator for enough room to inspect wire, remove top wire clamp & pulled another 71' before pulling up to 2,500lbs of tension, slack off and discuss options with superintendent.		Yes	
14:30	15:15	0.75	9.25	DOWNTIME	No	Re-install top wire clamp & cut wire 6' above clamp, strip out remaining +/- 650' of wire thru WL rams. Recovered all Wire.		Yes	
15:15	21:00	5.75	15.00	DOWNTIME	No	LD Lubricator. Cut off 2,100' of WL. Change Packing on Lubricator. Rehead WL.		Yes	
21:00	01:15	4.25	19.25	GENERAL OPERATIONS	No	SimOps - waiting on adjacent well		Yes	
01:15	06:00	4.75	24.00	DOWNTIME	No	Awaiting CTU to arrive on location		Yes	

NPT									
Type	Subtype	Des	Start Date	End Date	Failed Item	Accountable Party	Dur (Net) (hr)		
SURFACE EQUIPMENT	WIRELINE	Stuck Downhole pumped off tool. WL Stuck in grease tubing.	10/14/2017 20:00	10/15/2017 06:00		PRO OIL AND GAS SERVICES LLC	10.00		
SURFACE EQUIPMENT	WIRELINE	Clamp off WL & SI WL rams #2 & #3, Bleed off pressure & monitor, Pull birds nest through tubes.	10/15/2017 06:00	10/15/2017 09:30		PRO OIL AND GAS SERVICES LLC	3.50		
OTHER	WEATHER	Severe weather in the area	10/15/2017 09:30	10/15/2017 12:30		SABLE PERMIAN RESOURCES LAND, LLC	3.00		
SURFACE EQUIPMENT	WIRELINE	Continue to pull remaining +/- 800' of wire out of hole	10/15/2017 12:30	10/15/2017 17:00		PRO OIL AND GAS SERVICES LLC	4.50		
SURFACE EQUIPMENT	WIRELINE	Awaiting CTU Fishing Ops	10/15/2017 17:00	10/16/2017 06:00		PRO OIL AND GAS SERVICES LLC	13.00		

Safety Checks					
Time	Type	Inspected By	Description		
06:00	SAFETY MEETING	Chris Cobb/Slade Sears	PJSM PPE for acid and silica hazard		
06:00	SAFETY MEETING	Tim Milam/ Jerry Gosa	PJSM PPE Coil Expectations - Wireline issues		
06:00	SAFETY MEETING	Chris Cobb/Slade Sears	PJSM PPE & spotting in CTU		

Stimulations Summary					
Type	Stim/Treat Company	Start Date	End Date	Volume Clean Total (bbl)	Proppant Total (lb)
SAND FRAC	HALLIBURTON ENERGY SERVICES	10/4/2017		120,340.70	9,465,198.0