SABLE PERMIAN RESOURCES, LLC **Daily Completion Partner Report**

Report Date AFE# Total AFE 9/29/2017 1550467 4,547,178

UNIVERSITY 11 RE 931HS WELL NO. 155

API 42383398300000	State TEXAS	Coun REA		Well Config HORIZONTAL	Ground Elev 2,666.00	ration (ft)	RKB (ft) 21.00	Well Status COMPLETION		Well Sub-Status COMPLETING	Completion Date
Job Information											
Job Category COMPLETION			Primary Job Type COMPLETION - ORIGINAL						Start 9/18/2		End Date
AFE Number 1550467										Cum Field Est (Cost) 160,971	
Number of Stages (ft)			Lateral Length (ft) 9,865			Time Since LTI (days)			Time	Time Since Reportable Incident (days)	

Daily Contacts

Contacts
COMP ENG, CORLEY WALTERS, ; COMP SUPT, BEN MCCORMICK,

Daily Operations

Operations Summary
MIRU flow iron & tank, PTST iron, NU goat head & crown valve, set zipper manifold, RU water transfer to working tanks, RDMO iron from pump down line that is going out at the end of the month.

Pressure test goat head and crown valves 9800 psi Test good. Bleed off and secure well

Planned Operations
Replace iron on pump down line, spot in office trailer.

Time Log								
Start Time	End Time	Dur (hr)	Cum Dur (hr)	Activity	Inactive?	Comments	Unschd Type	NPT
06:00	07:30	1.50	1.50	INACTIVE	Yes	WSI & secure.		No
07:30	08:00	0.50	2.00	SAFETY MEETING	No	PJSM		No
08:00	12:00	4.00	6.00	RIG UP/DOWN	No	MIRU 2" flow iron & tank, set anchors for flow line, MIRU water transfer to the back of working tanks, take out iron that was going out of date this month on pump down line.		No
12:00	13:45	1.75	7.75	PRESSURE TEST	No	PTST flow iron, 500 psi low 5 min & 9,800 psi high 15 min.		No
13:45	16:00	2.25	10.00	RIG UP/DOWN	No	NU 7-1/16" 10M goat head w/ 7-1/16" 10M x 5-1/8" 10M change over spool & 5-1/8" 10M crown valve, spot in 3 way zipper manifold & NU single 7-1/16" 10M goat head on frac side.		No
16:00	19:00	3.00	13.00	STANDBY	No	Wait on well head repairs on off-set well.		No
19:00	19:30	0.50	13.50	PRESSURE TEST	No	Pressure test goathead/crown valve. 9800 psi Test good		No
19:30	06:00	10.50	24.00	INACTIVE	No	Well SI and secure		No

Safety Checks

Time	Туре	Inspected By	Description
07:30	SAFETY MEETING	Chris Cobbs	Discuss & review JSA's, Discuss todays agenda.