

## **DRILLING REPORT**

		UL Ame			14-21 1H	4-21 1H					CONTRACTOR: Cactus												Cactus	s 139	
RPT	August	7, 2017		ΔĐ	1#:	/2/Q53°	38760000		SPUD DATE: DFS:						CASING			Į v	VT	GRD	M	D	TVD		
					Al	1#.	424300	36700000		REP	ORT NO:	-													
		Phantor	n (Wolf								DOL:	_							1						
ELEV: MD: 80				RKB:			LAST B			OP TEST: 8/6/17															
24 H	R FTG:				HRS D	RLG:			CS	GHD:															
DRILLING I	ELLIID																			- CL	HOE T	EQT.			
TIME	MW	FV	WL	3R	PM	6RPM	l P	H CAI	KE GE	LS (10	0s/10m/30	Om)	PV		YP C	CL	K	Pf	Mf			OIL	LGS	HTHP	
									R				PUMP		PR	ESS			Н						
														#1		SPM									
															#2										
BIT DATA																									
NO.			SIZE		MAKE			T	'PΕ	SI	ER NO.	NO	OZZLES		RE-RUN	IN	OUT	FEE1	ET HRS		W	DВ	RPM	ROP	
BIT NO.			INNI	ER		C	DUTER		DULL		LC	ЭС		5	SEAL	GA	UGE	0.	THER	2	R	Р			
HYDRAULI	CS DAT		_					T=								I		T = .							
PUMP	PUMP MAKE			MODEL			L	LINER STK		ыK	SPM	SPM PS		3PN	I GPS	EFF %	ECD	ECD AV D		P AV DC		BIT HHP		PUMP HHP	
BHA	ION!		I																						
DESCRIPTION:  LENGTH BHA WT. A								AIR BHA W						NT.	MUD		Н	ON JA	ARS	Τ					
ROT. WT.					P.U. WT.								S.O. WT.						TORQUE						
TIME MADE UP					DATE MAD			DE UP					TIME PU		LED			D.	DATE PUL		_LED				
SURVEY DATA  MD					ANGLE			AZIMU		1		TVD			N/S	COORDINATES			E/W V		/. SECTION		DLS		
															,										
														+						-					
CONSUMA	BLES			DIES	SEL FUE	EL (gal	) Rvcd/L	Jsed/On F		A	TIONS	T18.6			RILL H2O	(gal) Ro	vd/Used/	On Har	nd:						
FROM	Т	0	HR	s		CODE	:	1	UF	EKA	TIONS	I IIVII	LU	G								Start M	MD	End MD	
06:00	18:00		12.0				Rig Up \	Rig Up Vibrating hose to Top Drive, Function Check Top Drive w/Cactus Tech, Install Swivel Packing, R/U Geronimo Line, Install IBOP, Saver Sub, Manual Valve, & Top Drive Back up													80		80		
							wrench,	radwing, NO deforming Line, instant top: , saver sub, wantar varie, a 10p blive back up wrench, Install Hydraulic Lines on BOP & BOP Test Flange, Put Slide on Centrifuge, Set Open Top Tanks under dryer shakers, hook up all hoses from Tar											Tonk						
							Farm to		ie on Centifluge, Set Open Top Tanks under dryer snakers, nook up all noses from Tan Rig Tanks, Install drive overs, R/U Flare Line & Ignighter								alin								
18:00	06	:00	12.	0	Rig Up & Tear Down		Install Compression Rings on Top Drive, Strap, OD's, ID's on 8" DC's, 6.5" DC's, HWDP Ready floor equipment to pick up BHA, Slips, Collar Clamps, Etc													80		80			
								Change	Change Dies on ST-80																
								Begin P	Perform Pre-Spud Inspection Begin P/U HWDP & Collars, racking in derrick *Tested BOP & Choke Manifold Offline																
								resteu	BOF &	CHOKE	iviaiiiioiu	Oiiii	16												
																					T				
																					+				
																					_				
																					+		+		
																					+				
тот	AL HRS	<b></b>	24.	0																					
WEATHER				'																					
GEN. CONI		S:		Fore		oudy	of thund	WIND S erstorms.		F Win		13 M		_	WIND E	DIRECTI	ON:	EN	IE .		TEMF	<b>'</b> :		73	
COMINIENT	J.			li ote	uasi. Ul		or thunde				rmation Ma				Ve	r 0831.1	6br								